

CATERHAM

OWNER TECHNICAL UPDATE NOTICE

*All updates are available from either
Caterham Aftersales, Dartford or Caterham Midlands, Leicester.*

Update number	001
Date of release	31/07/07

Applicable to	CSR260
Build period	Up to March 2007

Summary	<i>Improve driveability and negate possible shunt (Kangaroo) effect.</i>
---------	---

Caterham Cars are aware that the early CSR260 engine variant may suffer from shunt on light throttle, reducing driveability.

The route cause has been identified as the throttle return spring not being sufficient to prevent the driver's foot reacting from inertia when driving on light throttle.

A revised spring specification with increased spring stiffness is now available to resolve the shunt issue. In addition we have revised the calibration to improve general drivability.

These updates are available free of charge to all genuine CSR260 vehicles fitted with original equipment. They are not suitable for DIY installation.

For further information or to book a car in for an update to be fitted, please contact Caterham Aftersales (01322 625 804) or Caterham Midlands (01455 841616).